

When using the filler, always **keep the tip of the filler higher than the tail** of the filler. Otherwise, the tip of the cartridge will be pointing downward, and liquid CO_2 will flow into the regulator and block the flow of gas.

Tilting the enclosure at a 45 degree angle when filling will prevent this.

A blockage will clear by itself in 10-15 seconds, and it won't hurt the filler, but it greatly slows down the filling process.